EVALUATION INSTRUMENTS

plastic 6-inch 360° goniometer





Intended Purpose: permits observation of joint's axis of motion, and range of motion

- 360° head has three scales for ease of use
- primary scale reads in 1° increments
- · goniometer arm has a linear scale in inches and centimeters
- goniometer arm remains at measurement until reset

other goniometer styles and sizes available:

12 inch 360°12	-1000
8 inch 360°12	-1001
6 inch 360°12	-1002
6 inch 180° pocket12	-1005
6 inch 360° rulongmeter12	-1006
3 inch -30° to 120° finger	-1012

^{*} available standard or with white HiRes® strip behind numbers (add HR to end of product code for HiRes® model)

Measurement Tolerance

This device measures inches and centimeters with a tolerance of ±0.04 inches (±1 millimeter) and degrees with a tolerance of ±1 degree.

Disposal Method

Dispose of item in accordance with the local/regional/national/ international regulations.

WARNING:

- Clean and disinfect device before and after each patient use
 - Verify measurement markings are clearly visible
- Ensure smooth operation of all moving parts
- Align device properly with anatomical landmarks
- Apply gentle pressure during measurements
- Stop if patient reports pain or discomfort
- Store flat to prevent warping
- Replace if accuracy becomes compromised
- Do not attempt to bend or modify the device



Fabrication Enterprises Inc 250 Clearbrook Road, Suite 240 Elmsford, NY 10523 (USA) tel: +1914-345-9300 + 800-431-2830 fax: +1914-345-9900 + 800-634-5370 FabEnt.com











