

360° clear plastic goniometer, 12 inches





Intended Purpose: Permits observation of joint's axis of motion, and range of motion.

- 360° head has three scales for ease of use
- primary scale reads in 1° increments
- goniometer arm has a linear scale in inches and centimeters
- goniometer arm remains at measurement until reset

## other goniometer styles and sizes available:

12 inch 360°	12-1000*
8 inch 360°	12-1001*
6 inch 360°	12-1002*
6 inch 180° pocket	12-1005*
6 inch 360° rulongmeter	12-1006*
3 inch -30° to 120° finger	12-1012*

<sup>\*</sup> available standard or with white HiRes™ strip behind numbers (add HR to end of product code for HiRes™ model)

## **Measurement Tolerance**

This device measures inches and centimeters with a tolerance of ±0.04 inches (±1 millimeter) and degrees with a tolerance of ±1 degree.

## **Disposal Method**

Dispose of item in accordance with the local/regional/national/ international regulations.



## WARNING:

- Clean and disinfect device before and after each patient use
- Verify measurement markings are clearly visible
- Ensure smooth operation of all moving parts
- Align device properly with anatomical landmarks
- Apply gentle pressure during measurements
- Stop if patient reports pain or discomfort
- Store flat to prevent warping
- Replace if accuracy becomes compromised
- Do not attempt to bend or modify the device



Fabrication Enterprises Inc 250 Clearbrook Road, Suite 240 Elmsford, NY 10523 (USA) EI : +1-914-345-9800 • 800-431-2830 fax: +1-914-345-9800 • 800-634-5370 FabEnt.com





